



# febi 38548, 100590



**To Fit:**

Porsche Cayenne, Volkswagen Touareg



## Propshaft Centre Support

**Problem**

Cracking noises can be heard and harsh vibrations can be felt in the passenger compartment, especially when the vehicle is accelerating or decelerating.

**Cause**

The cause of this can come from a worn propshaft centre bearing rubbing against the propshaft. The rubber of the bearing may split due to wear and tear, leading to noises and vibrations. The worn centre bearing support allows the propshaft to move vertically when changing gear, leaving the bearing unable to support the propshaft. As a result, the component should be replaced.

**Solution**

The propshaft centre bearing is not available separately from the vehicle manufacturer and can only be ordered with the complete propshaft. This makes the repair very expensive. febi offers a repair kit – 100590. This includes the propshaft centre support with integrated roller bearing, protective boot, retaining clip, and grease.

For more technical information please visit: [partsfinder.bilsteingroup.com](http://partsfinder.bilsteingroup.com)